

Sample Building List

Address	Number of Stories	Torsional?	Frame or Shear Wall	Photo	Other
1 Main	2	Yes, corner building	Frame with masonry infill	1, 2	Adjacent wood frame buildings with no gap at property lines
2 3 rd St	2	No	Shear wall	3, 4	See what appears to be wall anchors at roof
66 Oak	1	Yes, open front	?	5, 6	It looks like concrete, should verify
53 Elm	3	No	Frame	7, 8	Looks like first floor is soft story, much greater floor height

